

## Handwheels • DIN 950 light metal

24590.0450



### Product Description

Hub machined; rim turned and mirror-finished on all sides, non-machined surfaces cleanly blasted.

### Material

#### Handwheel

- Light metal Al

#### Machine handle DIN 39 EH 24450.

- Steel, turned, zinc-plated by galvanization, passivated

### Assembly

Shaft-end washers EH 22270. for axial fastening.

### More information

### Further products


- Shaft-End Washers
- Rotating Machine Handles, DIN 98

## Drawing



The orientation of the hub keyway may be different than shown in the drawing.

## Order information

| Dimensions   |             |       |       |       |            |       |            | Number of spokes<br>$z$ | Corresponding machine handle<br>DIN 39 / DIN 98 | <br>[g] | Art. No.   |
|--|-------------|-------|-------|-------|------------|-------|------------|-------------------------|---|--|------------|
| $d_1$  | $d_2$<br>H7 | $d_3$ | $d_4$ | $d_5$ | $l_1$<br>~ | $l_2$ | $l_3$<br>~ |                         |   |  |            |
| without hub keyway, with machine handle EH 24450., assembled, form B-F/G (formerly: F 4) – picture 2 |             |       |       |       |            |       |            |                         |   |  |            |
| 400  | 30          | 65    | M16   | 36    | 63         | 38    | 112        | 5                       | 36  | 4210   | 24590.0450 |

## Application example



## Compliance

### RoHS compliant

Contains lead - compliant according to exceptions 6a / 6b / 6c.

### Contains SVHC substances >0,1% w/w

Contains lead - SVHC list [REACH] as of 27.06.2024.

### Contains Proposition 65 substances



Lead can cause cancer and reproductive harm from exposure  
<https://www.P65Warnings.ca.gov/>

### Free from Conflict Minerals

This product does not contain any substances designated as "conflict minerals" such as tantalum, tin, gold or tungsten from the Democratic Republic of Congo or adjacent countries.